



MERCEDES Sprinter: BW9758			
Vinnnumber:	WDB9061351N532791	Versionname:	SPRINTER CH1C 316
First Registrationdate:	31/10/2012	Fiscalpower:	3500kg LWB 163PK Spec.
Expertise Mileage:	145762	Power Kw:	120
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV15
Number of doors:	2		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	
Windows electric F	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining semi-artificial leather

Limited Technical Inspection			
Tires wear profile:	OK	Battery functioning:	Yes
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Wiper fluid level:	OK
Transmission:	OK	Lighting:	OK
Handbrake:	OK	Wiperblades:	OK

Degree of wear				
	235/65/16/115 R Steel			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment			
Spare wheel:	Yes	Jack:	Yes

Total cost ex VAT:	1970,64
Mirror side blinker L, Broken, E - Replace:	49,00









Front bumper, Scratch(es), Acceptable:	0,00
--	-------------

No pictures to display

Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete):	232,88
--	---------------



Roof, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F R, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Sidewall panel RL, Hole, E - Replace	400,00
	
Wing F L, Bump(s), LI - Repair and paint (complete)	213,13
	
Door F L, Bump(s), Le - Replace and paint	847,88
	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Damaged, Acceptable	0,00
	
Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Damaged, Acceptable	0,00
	
Interior, Stain, Cleaning	50,00
	
Wing F R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Door trim F L, Scratch(es), E - Replace	91,50



Fuel tank stopper, Bump(s), E - Replace	75,00
---	-------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Dashboard, Scratch(es), Acceptable	0,00
------------------------------------	------

No pictures to display

Aerial, Broken, E - Replace	11,25
-----------------------------	-------

