



**VOLKSWAGEN TIGUAN: 1FTS061**

Vinnnumber:	<b>WVGZZZ5NZEW543718</b>	Versionname:	<b>TIGUAN Trend&amp;Fun BM Tech.110PK</b>
First Registrationdate:	<b>22/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>93111</b>	Power Kw:	<b>81</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2632</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Type of headlighting	<b>Headlighting Halogen</b>	Luggage cover	
Type of Lining	<b>Lining fabrics</b>	Type of Tow bar	<b>Tow bar fixed</b>
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/65/16/98 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>0,00</b>
-------------------	-------------


Rearview mirror housing R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Engine protective plate, Tear, E - Replace	<b>72,00</b>
--	--------------



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>438,35</b>
---	---------------



Cigar lighter, Incomplete, E - Replace	<b>18,00</b>
--	--------------



Interior, Stain, Cleaning 96,00



Door F L, Bump(s), LI - Repair and paint (complete) 318,35



Door moulding Lower R R, Scratch(es), E - Replace 114,00



Door moulding Lower F R, Scratch(es), E - Replace 114,00



Tailgate, Bump(s), Le - Replace and paint 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar R, Bump(s), PDR - Knock out without painting 63,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Boot cover, Missing, E - Replace 50,00

