


VOLKSWAGEN Golf: 1E2B291

Vinnumber:	WVWZZZAUZDP070133	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	25/04/2013	Fiscalpower:	
Expertise Mileage:	116760	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3831
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/91 MS Steel			
Winter tyres:	Fr.L.	Semperit: 3 mm	Fr.R.	Semperit: 3 mm
	Re.L.	Semperit: 3 mm	Re.R.	Semperit: 3 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	2796,24
-------------------	---------

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Door F L, Bump(s), LI - Repair and paint (complete)	318,35
---	--------



Wheel cover R R, Missing, E - Replace	30,00
---------------------------------------	-------



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Roof, Scratch(es), LI - Repair and paint (complete)

481,50



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Sill outer L, Bump(s), LI - Repair and paint (complete)

310,50



Bodywork, Stain, Forfeit

48,00



Tailgate, Bump(s), LI - Repair and paint (complete)

325,68



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Wheel cover F R, Missing, E - Replace

30,00

