



RENAULT Clio: NR7488

Vinnnumber:	VF17R040H49875417	Versionname:	CLIO IV BRE Authentique
First Registrationdate:	6/12/2013	Fiscalpower:	75PK
Expertise Mileage:	106372	Power Kw:	55
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1126
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	
Cruise Control	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	185/65/15/88 T Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1690,45
--------------------------	----------------

Brand badge, Broken, E - Replace	50,00
---	--------------



Bumper grille, Broken, E - Replace	74,00
---	--------------



Backrest cover F L, Burned, E - Replace	312,00
--	---------------



Roof pillar L, Bump(s), LI - Repair and paint (complete) 224,14



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Bonnet, Bump(s), PDR - Knock out without painting 123,00



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

De-icer nozzle internal L, Broken, E - Replace 68,00



Seat cover F L, Burned, E - Replace 312,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Mats, Burned, Repair/replace (lump sum) 48,00



Headlight R, Scratch(es), 67 - Polish 55,19

