



VOLKSWAGEN Passat: 1EAB118			
Vinnnumber:	<b>WVWZZZ3CZDE052496</b>	Versionname:	<b>PASSAT VAR Comfortline BMT 105PK</b>
First Registrationdate:	<b>1/10/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>63993</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Light Beige</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>4733</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>HD</b> Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
Summer tyres:	<b>215/55/16/93 W LightMetal</b>			
	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1016,80</b>
Door R L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>



Bumper cover R M, Crack, E - Replace	<b>40,00</b>
--------------------------------------	--------------



Bumper R, Bump(s), LI - Repair and paint (complete) 259,80



Wing R L, Bump(s), LI - Repair and paint (complete) 380,20



Mirror side blinker R, Broken, E - Replace 30,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

