



VOLKSWAGEN Golf: 1DOL446

Vinnnumber:	WVWZZZ1KZCM700156	Versionname:	GOLF BRE Trendl.BM DPF DSG 105PK Aut.
First Registrationdate:	6/07/2012	Fiscalpower:	
Expertise Mileage:	80006	Power Kw:	77
Bodytype:	Break	Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1433
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/95 H LightMetal			
Summer tyres:	Fr.L.	Fulda: 3 mm	Fr.R.	Fulda: 3 mm
	Re.L.	Fulda: 4 mm	Re.R.	Fulda: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1938,25
-------------------	---------







Wing F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

	Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	452,20
	Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Rearview mirror housing R, Broken, E - Replace	25,00
	Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
<i>No pictures to display</i>		
	Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
	Windscreen, Scratch(es), E - Replace	0,00
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Roof, Chemical polution, LI - Repair and paint (complete)	481,50
	Seat cover F L, Burned, Smart repair	64,32
