



VOLKSWAGEN TIGUAN: 1EPI491

| | | | |
|-------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WVGZZZ5NZDW591831 | Versionname: | |
| First Registrationdate: | 14/02/2013 | Fiscalpower: | |
| Expertise Mileage: | 207277 | Power Kw: | 81 |
| Bodytype: | SUV | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3211 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--|
| Radio CD | | Sun Roof electric | |
| GPS storage | HD | Panoramic roof | |
| GPS storage | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|---------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | NOT OK |
| Exhaust gass | OK | Lighting | NOT OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |


Degree of wear

| | | | | |
|----------------------------------|-------|----------------------|-------|----------------------|
| 215/65/16/98 H LightMetal | | | | |
| Summer tyres: | Fr.L. | Hankook: 3 mm | Fr.R. | Hankook: 3 mm |
| | Re.L. | Hankook: 3 mm | Re.R. | Hankook: 3 mm |

Assistance equipment


| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|----------------------------------|---------------|
| Total cost ex VAT | 195,00 |
| Interior, Stain, Cleaning | 24,00 |



| | |
|--|-------------|
| Roof, Stone chip(s), Acceptable | 0,00 |
|--|-------------|

| | |
|---|-------|
| Bonnet, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Trunk lid covering R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Tailgate, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Bump(s), PDR - Knock out without painting | 82,80 |



| | |
|--|-------|
| Windscreen, Stone chip(s), Windscreen repair | 88,20 |
|--|-------|

