



SKODA Superb: 1EBQ354			
Vinnnumber:	<b>TMBJJ73TXD9024985</b>	Versionname:	<b>SUPERB COMBI GreenLine Active DPF 105PK</b>
First Registrationdate:	<b>12/10/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>181030</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1409</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>205/55/16/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>No</b>
Total cost ex VAT			<b>0,00</b>
Rocker panel inner R R, Bump(s), LI - Repair and paint (complete)			<b>115,56</b>



Interior, Stain, Cleaning	<b>50,00</b>
---------------------------	--------------





Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Compressor, Missing, E - Replace 75,00



Bumper R, Damaged, Le - Replace and paint 766,80



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Reflector, Crack, E - Replace 50,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Wheel cover F R, Scratch(es), E - Replace 36,00



Tailgate, Bump(s), Acceptable 0,00

*No pictures to display*