



BMW 1: 1EDW734

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnnumber: | WBA1N31020J710207 | Versionname: | 1 SPORTSHATCH 116d Eff.Dyn.Ed.116PK |
| First Registrationdate: | 2/11/2012 | Fiscalpower: | |
| Expertise Mileage: | 150681 | Power Kw: | 85 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | | |
| Number of doors: | 3 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | Luggage cover |
| Windows electric F | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting: | Headlighting Halogen |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Manual climate control |
| Adaptive cruise control | |

Limited Technical Inspection

| | | | |
|---------------------|---------------|---------------------|---------------|
| Airco functioning | NOT OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | NOT OK |
| Idle position | NOT OK | Clutch test | NOT OK |
| Engine startingtime | NOT OK | Wiper fluid level | OK |
| Exhaust gass | NOT OK | Lighting | NOT OK |
| Transmission | NOT OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 V LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 231,12 |
|-------------------|---------------|

| | |
|--|---------------|
| Bumper corner R R, Scratch(es), It - Spot repair | 115,56 |
|--|---------------|



| | |
|---|---------------|
| Bumper F R, Scratch(es), It - Spot repair | 115,56 |
|---|---------------|

