



IVECO DAILY: 1PNH631

Vinnnumber:	ZCFC635A005106829	Versionname:	3.0 TD DRW 35C15V 3520L
First Registrationdate:	11/08/2016	Fiscalpower:	MRF 3500
Expertise Mileage:	22139	Power Kw:	107
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	TRU15
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Windows electric F:		Type of Tow bar:	Tow bar fixed
Type of headlighting:	Headlighting Halogen		
Type of Lining:	Lining artificial leather		

Limited Technical Inspection

Tires wear profile:	OK	Battery functioning:	Yes
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Wiper fluid level:	OK
Transmission:	OK	Lighting:	OK
Handbrake:	OK	Wiperblades:	OK

Degree of wear

	195/75/16/110 C Steel			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 2 mm	Re.R.	Continental: 2 mm

Assistance equipment

Spare wheel:	No	Jack:	Yes
--------------	-----------	-------	------------

Total cost ex VAT	1569,20
-------------------	----------------

Registration Document, Missing, E - Replace	150,00
---	---------------



Spare wheel, Missing, E - Replace	153,60
-----------------------------------	---------------



Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Trunk door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Bonnet, Bump(s), PDR - Knock out without painting 82,80



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 100,00



Bumper corner R L, Scratch(es), Smart repair 110,64



Molding trunk, Damaged, E - Replace 84,00



Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R R, Scratch(es), Smart repair 110,64



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Trunk door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Certificate Of Conformity, Missing, E - Replace 150,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display