


PEUGEOT Boxer 330: 1DVC711

Vinnnumber:	VF3YBUMFC12169024	Versionname:	BOXER 333 B/F LWB L3H2 FAP 150PK
First Registrationdate:	6/09/2012	Fiscalpower:	
Expertise Mileage:	78947	Power Kw:	110
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV18
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Rear parking sensors
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/70/15/109 S Steel			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	747,75
-------------------	---------------

Bodywork, Not original part, Acceptable	0,00
---	-------------

No pictures to display

Sidewalll RR (LCV), Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Trunk door R R, Bump(s) and scratch(es), It - Spot repair	115,56
---	---------------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)	361,13
---	---------------



Engine protective plate, Tear, E - Replace	64,00
--	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearlight L, Crack, E - Replace	91,50
---------------------------------	-------



Sidewall RL (LCV), Scratch(es), It - Spot repair	115,56
--	--------



Sliding door R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display