



## PEUGEOT 5008: 1FGK428

Vinnumber:	<b>VF30A9HD8DS045297</b>	Versionname:	<b>5008 e-HDi Allure FAP BMP 115PK Aut.</b>
First Registrationdate:	<b>21/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>117763</b>	Power Kw:	<b>84</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1527</b>
Maintenance:	<b>+1700</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD		Panoramic roof	
GPS storage		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar removable</b>
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear


	<b>215/55/16/93 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Firestone: 6 mm</b>	Fr.R.	<b>Firestone: 6 mm</b>
	Re.L.	<b>Continental: 3 mm</b>	Re.R.	<b>Continental: 3 mm</b>

## Assistance equipment

Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
--------------------	------------	------	------------






















Total cost ex VAT 1735,33

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 550,50



Tailgate, Bump(s), LI - Repair and paint (complete)

373,68

			
			
Windscreen, Scratch(es), E - Replace			0,00
			
Alloy rim R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R R, Bump(s), PDR - Knock out without painting			63,00
			
Radio, Worn, Acceptable			0,00
			
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80
			
Alloy rim R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Bump(s), I - Repair			48,00
			
Door F R, Bump(s), LI - Repair and paint (complete)			438,35
			
			
Interior, Dirty, Cleaning			50,00



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*