



TOYOTA GRAND PRIUS+: 1LSN714

Vinnnumber:	JTDZ53EU803117242	Versionname:	1.8 VVT-I HYBRID ACTIVE
First Registrationdate:	24/11/2015	Fiscalpower:	AUTO
Expertise Mileage:	34284	Power Kw:	100
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3833
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/92 V Steel			
Winter tyres:	Fr.L.	Yokohama: 3 mm	Fr.R.	Yokohama: 3 mm
	Re.L.	Yokohama: 3 mm	Re.R.	Yokohama: 3 mm

Assistance equipment

Total cost ex VAT	1066,59
Wheel cover F L, Scratch(es), E - Replace	30,00






















Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Wing R R, Bad repair, Acceptable	0,00
 	
Wing R L, Bump(s), Acceptable	0,00
No pictures to display	
Wing F L, Bump(s), Acceptable	0,00
No pictures to display	
Door R R, Bad repair, Acceptable	0,00
 	
Interior, Dirty, Cleaning	50,00
  	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
  	
Wheel cover R L, Scratch(es), E - Replace	30,00
 	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
 	
Bumper R, Scratch(es), Smart repair	110,64
  	
Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
 	
Protection plate M, Tear, E - Replace	74,00
