



VOLKSWAGEN Golf Break: 1EEW629

Vinnumber:	WVWZZZ1KZDM633572	Versionname:	GOLF BRE Trendline BlueMot.DPF 105PK
First Registrationdate:	12/11/2012	Fiscalpower:	
Expertise Mileage:	185583	Power Kw:	77
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2303
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1165,08
--------------------------	----------------

Wing F L, Chemical polution, LI - Repair and paint (complete)	220,18
--	---------------



Bonnet, Stone chip(s), Acceptable	0,00
--	-------------

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
--	---------------



Door F R, Bump(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), E - Replace	0,00
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35