




SKODA Octavia: 1BOP654			
Vinnnumber:	TMBHT21Z7C2018720	Versionname:	OCTAVIA COMBI Ambiente DPF 105PK
First Registrationdate:	19/07/2011	Fiscalpower:	
Expertise Mileage:	203646	Power Kw:	77
Bodytype:	Break	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1508
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	195/65/15/91 T LightMetal			
	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1516,56
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00
---	--	--	--------------



Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)			115,56
--	--	--	---------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Trunk lid covering R, Scratch(es), Smart repair 110,64



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56

