



**CITROEN BERLINGO: 1HZT996**

Vinnumber:	<b>VF77B9HN0EJ745658</b>	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	<b>76453</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2614</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	
Windows electric F	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Other: 3 mm</b>	Fr.R.	<b>Other: 3 mm</b>
	Re.L.	<b>Other: 5 mm</b>	Re.R.	<b>Other: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	2253,93
Interior, Dirty, Cleaning	100,00



Wheel cover F R, Scratch(es), E - Replace	22,50
---	-------



Bumper R, Bump(s) and scratch(es), Smart repair 110,64



Door trim F L, Scratch(es), E - Replace 91,50



Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 165,13



Trunk door R L, Bump(s) and scratch(es), It - Spot repair 115,56



Trunk door R R, Bump(s) and scratch(es), It - Spot repair 115,56



Trunk door R R, Missing, E - Replace 74,00



Rocker panel inner R R, Damaged, LI - Repair and paint (complete) 115,56

Rocker panel inner R R, Damaged, LI - Repair and paint (complete) 115,56



Internal Boot Lining R, Damaged, Smart repair 110,64



Wheel cover R R, Scratch(es), E - Replace 22,50



Front bumper, Incomplete, E - Replace 32,00



Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Door R R, Damaged, E - Replace 29,60




Door moulding Lower R L, Scratch(es), E - Replace 91,50




Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 361,13





Internal Boot Lining L, Damaged, Smart repair

110,64

