



VOLVO V60: 1FBT898

Vinnumber:	YV1FW31A1D1139979	Versionname:	V60 D3 Kinetic St/St
First Registrationdate:	17/05/2013	Fiscalpower:	136PK
Expertise Mileage:	59180	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Body color	GRIS
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	No	Oil level	OK
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Sun Roof electric	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	No
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/97 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1425,71
Door panel R L, Scratch(es), E - Replace	114,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 366,35



Seat cover R L, Stain, Cleaning 50,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel aperture R R, Scratch(es), LI - Repair and paint (complete) 115,56



Door panel R R, Scratch(es), E - Replace 114,00



Door panel F L, Hole, E - Replace 114,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

