



PEUGEOT 508: 1GEP478			
Vinnnumber:	VF38URHC8DL057080	Versionname:	508 SW RXH BMP STT 163PK Aut.
First Registrationdate:	17/01/2014	Fiscalpower:	
Expertise Mileage:	101291	Power Kw:	120
Bodytype:	Break	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Hybrid Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2515
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Panoramic roof
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining leather
Head-up Display	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	245/45/18/100 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment	
	Runflat Yes
Total cost ex VAT	2450,76
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------




Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35




Rear window, Scratch(es), E - Replace 370,00




Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Dirty, Cleaning 100,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35

Door R L, Scratch(es), Lt - Repair and paint (complete) 310,35



Wing F R, Scratch(es), Lt - Spot repair 115,56



Alloy rim F R, Scratch(es), Lt - Repair and paint (complete) 95,00

