



| VOLKSWAGEN GOLF VII: 1HVS891 | | | |
|------------------------------------|-------------------------|--------------|-----------------------------------|
| Vinnumber: | VWVZZZAUFW113245 | Versionname: | 1.6 TDI 77KW BMT TRENDLINE |
| First Registrationdate: | 15/10/2014 | Fiscalpower: | |
| Expertise Mileage: | 78907 | Power Kw: | 77 |
| Bodytype: | Hatchback | Body color: | Dark Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3310 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |
| Adaptive cruise control | |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| Degree of wear | | | | |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 V LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

| Assistance equipment | | | |
|---|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 306,80 |
| Rearview mirror housing R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Front bumper, Scratch(es), LI - Repair and paint (complete) | | | 211,80 |



| | | | |
|--|--|--|--------------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |
|--|--|--|--------------|



| | |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |