



SKODA OCTAVIA COMBI: 1JPN051

Vinnnumber:	TMBJG7NE0F0128969	Versionname:	1.6 CRDI 77KW GREENTEC AMBITION
First Registrationdate:	2/02/2015	Fiscalpower:	
Expertise Mileage:	180145	Power Kw:	77
Bodytype:		Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3628
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	431,80
-------------------	--------

Front bumper, Stone chip(s), Acceptable	0,00
---	------

No pictures to display

Bodywork, Not original part, Remove lettering	0,00
---	------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace 0,00



Rocker panel inner R R, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Engine protective plate, Missing, E - Replace 89,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Battery F, Damaged, E - Replace 34,60



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display