



PEUGEOT BOXER: 1HLZ741

Vinnnumber:	VF3YUMFC12685279	Versionname:	
First Registrationdate:	25/08/2014	Fiscalpower:	
Expertise Mileage:	57217	Power Kw:	110
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV05
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/70/15/109 S Steel			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------


Total cost ex VAT	1130,89
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Rear panel, Scratch(es), It - Spot repair	115,56



Wheel cover F R, Missing, E - Replace	22,50
---------------------------------------	-------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Sidewall FR (LCV), Bump(s) and scratch(es), It - Spot repair 115,56



Wing R R, Bump(s), PDR - Knock out without painting 102,60



Interior, Dirty, Cleaning 100,00



Rear bulkhead lining, Crack, E - Replace 39,00



Sliding door R, Bump(s), LI - Repair and paint (complete) 382,02



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Missing, E - Replace 22,50

