




<b>BMW 5: YE8961</b>			
Vinnumber:	<b>WBAMX11000DU40646</b>	Versionname:	<b>5 TOURING 520dA 184PK Aut.</b>
First Registrationdate:	<b>22/08/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>126940</b>	Power Kw:	<b>135</b>
Bodytype:	<b>Break</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2503</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		





















<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>225/55/17/97 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 3 mm</b>	Fr.R.	<b>Pirelli: 3 mm</b>
	Re.L.	<b>Pirelli: 3 mm</b>	Re.R.	<b>Pirelli: 3 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>1843,08</b>
<b>Bumper F R, Scratch(es), It - Spot repair</b>			<b>115,56</b>



<b>Backrest cover F L, Damaged, E - Replace</b>	<b>408,00</b>
---	---------------

		Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
		Sill trim R, Scratch(es), It - Spot repair	115,56
		Door R L, Bump(s), PDR - Knock out without painting	63,00
		Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
		Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
		Air vent R M, Damaged, E - Replace	158,40
		Seat cover F R, Damaged, E - Replace	408,00
		Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>			
Wing R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
		Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
		Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>			
Dashboard, Damaged, Forfeit			24,00

