


PEUGEOT 508: 1EJY749

Vinnnumber:	VF38E9HD8CL081541	Versionname:	508 SW e-HDi Active BMP 115PK Aut.
First Registrationdate:	2/01/2013	Fiscalpower:	
Expertise Mileage:	180281	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3506
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1776,71
Front bumper, Damaged, Le - Replace and paint	735,00






Full screen GPS, Not functioning (well), P - Check	0,00
--	------

No pictures to display

Headlight L, Damaged, E - Replace	396,00
-----------------------------------	--------



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Bump(s) and scratch(es), It - Spot repair	115,56
	
Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
	
Sill outer L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	