



| SKODA Octavia: 1DOT944  |                          |              |  |
|-------------------------|--------------------------|--------------|--|
| Vinnnumber:             | <b>TMBHT21Z0D2028930</b> | Versionname: | <b>OCTAVIA COMBI GTec Ambition DPF 105PK</b> |
| First Registrationdate: | <b>10/07/2012</b>        | Fiscalpower: |  |
| Expertise Mileage:      | <b>128267</b>            | Power Kw:    | <b>77</b>                                    |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>Black</b>                                 |
| Gearbox:                | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                               |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>                             |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                    |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>4308</b>                                  |
| Number of doors:        | <b>5</b>                 |              |  |
| Number of seats:        | <b>5</b>                 |              |  |
| Number head rests:      | <b>5</b>                 |              |  |
| Rims summer:            | <b>Aluminium</b>         |              |  |
| Category:               | <b>Passenger Car</b>     |              |  |
| Oil level:              | <b>OK</b>                |              |  |

| Options                        |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position                | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission                 | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake                    | <b>OK</b> |                     |            |

| Degree of wear |                                  |                       |       |                       |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| Summer tyres:  | <b>195/65/15/91 T LightMetal</b> |                       |       |                       |
|                | Fr.L.                            | <b>Fulda: 6 mm</b>    | Fr.R. | <b>Fulda: 6 mm</b>    |
|                | Re.L.                            | <b>Uniroyal: 4 mm</b> | Re.R. | <b>Uniroyal: 4 mm</b> |

| Assistance equipment                                    |            |      |            |
|---|------------|------|------------|
| Spare wheel   | <b>Yes</b> | Jack | <b>Yes</b> |
| Total cost ex VAT                                       |            |      | 1280,23    |
| Bumper R, Scratch(es), LI - Repair and paint (complete) |            |      | 211,80     |



|   |       |
|---|-------|
| Door R L, Bump(s), PDR - Knock out without painting | 63,00 |
|---|-------|



Interior, Dirty, Cleaning 50,00



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Floor covering F L, Damaged, E - Replace 252,00



Wing R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), Acceptable 0,00

*No pictures to display*