



**OPEL Vivaro 2700: 1CRP351**

Vinnnumber:	<b>WOLF7A1A6CV618279</b>	Versionname:	<b>VIVARO 2700 B/F SWB L1H1(EU5)115PK</b>
First Registrationdate:	<b>10/02/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>252286</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2613</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/65/16/107 T Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Spare wheel **Yes**

Total cost ex VAT **830,25**

Floor covering F L, Hole, Smart repair **110,64**



Interior, Dirty, Cleaning **0,00**



Door F R, Bump(s), Acceptable **0,00**

*No pictures to display*

Bumper R, Scratch(es), It - Spot repair **115,56**



Rearlight R tailgate, Damaged, E - Replace 174,00



Front bumper, Bad repair, Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Missing, E - Replace 22,50



Windscreen, Damaged, E - Replace 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 158,85



Wheel cover F R, Missing, E - Replace 22,50



Front bumper, Scratch(es), It - Spot repair 115,56



Rearview mirror housing R, Scratch(es), Smart repair 110,64

