



VOLKSWAGEN Golf: 1GGO039			
Vinnnumber:	WVWZZZAUZEP557297	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	3/02/2014	Fiscalpower:	
Expertise Mileage:	138065	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1111
Number of doors:	2		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear			
Winter tyres:	195/65/15/91 T LightMetal		
	Fr.L.	Fr.R.	
	Bridgestone: 5 mm	Bridgestone: 5 mm	
	Re.L.	Re.R.	
	Bridgestone: 6 mm	Bridgestone: 6 mm	

Assistance equipment			
Spare tyre compact	Yes	Jack	Yes

Total cost ex VAT	1568,71
Ignition key, Missing, E - Replace	150,00

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Wing R L, Bump(s) and scratch(es), It - Spot repair 115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Scratch(es), E - Replace 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

