



BMW 4 COUPE: 1RSP402			
Vinnumber:	<b>WBA4R11080K525031</b>	Versionname:	<b>425d (155 kW)</b>
First Registrationdate:	<b>20/02/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>31628</b>	Power Kw:	<b>155</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3702</b>
Number of doors:	<b>2</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
GPS storage	Front parking sensors
GPS storage	HD Rear parking sensors
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining Alcantara</b>
Type of climate control	<b>Autom climate control</b>
Sport seats	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>255/40/18/95 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 7 mm</b>	Fr.R.	<b>Pirelli: 7 mm</b>
	Re.L.	<b>Pirelli: 7 mm</b>	Re.R.	<b>Pirelli: 7 mm</b>

Assistance equipment	
Runflat	<b>Yes</b>
Total cost ex VAT	<b>1548,80</b>
Door F R, Bump(s), PDR - Knock out without painting	<b>63,00</b>



Rearview mirror housing L, Scratch(es), 67 - Polish	<b>0,00</b>
---	-------------



Bumper R, Bump(s) and scratch(es), Le - Replace and paint 766,80



Door F L, Scratch(es), Acceptable 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16

