



**FORD Focus: 1EGP476**

Vinnnumber:	<b>WF0LXXGCBLC585369</b>	Versionname:	<b>FOCUS CLIP. ECONetic T.Trend 95PK</b>
First Registrationdate:	<b>27/11/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>156570</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Battery functioning	<b>Yes</b>
Clutch test	<b>NOT OK</b>

**Degree of wear**

	<b>205/55/16/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
------------	-----------	------------	-----------

<b>Total cost ex VAT</b>	<b>2667,46</b>
--------------------------	----------------

<b>Windscreen, Stone chip(s), Windscreen repair</b>	<b>58,80</b>
---	--------------



<b>Door R L, Scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>
--	---------------



<b>Wheel cover R R, Missing, E - Replace</b>	<b>30,00</b>
--	--------------



Sill outer R, Broken, E - Replace

123,00



Seat cover F L, Tear, E - Replace

360,00



Steel rim F R, Damaged, E - Replace

88,80



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

404,20



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Engine, Not functioning (well), P - Check

0,00



Seat cover F R, Burned, Smart repair

64,32



Headlight L, Scratch(es), E - Replace

396,00



Interior, Dirty, Cleaning 150,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Headlight R, Scratch(es), 67 - Polish 55,19



Boot carpet, Missing, E - Replace 100,00



Wheel cover R L, Missing, E - Replace 30,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler F R, Scratch(es), E - Replace 42,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Sticker removal 0,00



Tyre repair kit, Missing, E - Replace 175,00



Wheel cover F R, Missing, E - Replace 30,00



Wheel cover F L, Missing, E - Replace

30,00

