



<b>SKODA Octavia: 1CVQ940</b>			
Vinnumber:	<b>TMBCT21Z7C2133277</b>	Versionname:	<b>OCTAVIA BER GreenLine Ambition DPF 105PK</b>
First Registrationdate:	<b>7/03/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>70905</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3301</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Luggage cover
GPS storage	<b>HD</b> Rear parking sensors
GPS storage	
Windows electric F	
Cruise Control	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>195/65/15/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 3 mm</b>	Re.R.	<b>Goodyear: 3 mm</b>

<b>Assistance equipment</b>	
Repair kit	<b>Yes</b> Compressor <b>Yes</b>
Total cost ex VAT	<b>1215,76</b>
Wing R R, Scratch(es), LI - Repair and paint (complete)	<b>308,20</b>



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Front bumper, Scratch(es), It - Spot repair	<b>115,56</b>
---	---------------



Bumper R, Bump(s), LI - Repair and paint (complete)	211,80
---	--------



Rearlight L tailgate, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Sill outer R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Wing R L, Bump(s), LI - Repair and paint (complete)	308,20
---	--------



Door panel F L, Damaged, E - Replace	114,00
--------------------------------------	--------

