


SKODA Octavia: 1ETY931

Vinnnumber:	TMBHT61Z8D2136851	Versionname:	OCTAVIA COMBI GTec Ambition DPF 105PK
First Registrationdate:	20/03/2013	Fiscalpower:	
Expertise Mileage:	166440	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2511
Maintenance:	UITVOEREN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	NOT OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1185,84
-------------------	---------

Air vent R M, Broken, E - Replace	156,00
-----------------------------------	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s) and scratch(es), Acceptable 0,00



Door trim F R, Scratch(es), Smart repair 110,64



Rear window, Not original part, Remove lettering 25,00



Front bumper, Scratch(es), Acceptable 0,00



Door trim R R, Scratch(es), Acceptable 0,00



Headlight L, Not functioning (well), E - Replace 396,00



Maintenance, Maintenance, Execute 0,00



Wing F R, Scratch(es), Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R R, Scratch(es), Acceptable 0,00

