



TOYOTA Grand Prius Plus: 1HCB313

Vinnnumber:	JTDZ53EUX03098435	Versionname:	GRAND PRIUS+ Hybrid Lounge 98PK Aut.
First Registrationdate:	16/06/2014	Fiscalpower:	
Expertise Mileage:	84040	Power Kw:	73
Bodytype:	MPV	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2512
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar removable
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/50/17/95 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Total cost ex VAT	648,56
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00








Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Glove compartment lid, Scratch(es), Smart repair	110,64
--	--------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
Wing R L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		115,56
		
Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)		115,56
