



SEAT ALTEA: 1TMN302			
Vinnnumber:	<b>VSSZZ5PZCR031905</b>	Versionname:	<b>ALTEA</b>
First Registrationdate:	<b>17/05/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>65621</b>	Power Kw:	
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Registration Certificate Car (BE)	<b>No</b>		

Options	
Radio CD	Central consol F
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection	
Battery functioning	<b>Yes</b>

Degree of wear									
Summer tyres:	<b>205/55/16/91 V LightMetal</b>								
	<table border="1"> <tr> <td>Fr.L.</td> <td><b>Uniroyal: 7 mm</b></td> <td>Fr.R.</td> <td><b>Uniroyal: 7 mm</b></td> </tr> <tr> <td>Re.L.</td> <td><b>Bridgestone: 5 mm</b></td> <td>Re.R.</td> <td><b>Bridgestone: 5 mm</b></td> </tr> </table>	Fr.L.	<b>Uniroyal: 7 mm</b>	Fr.R.	<b>Uniroyal: 7 mm</b>	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>
Fr.L.	<b>Uniroyal: 7 mm</b>	Fr.R.	<b>Uniroyal: 7 mm</b>						
Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>						

Assistance equipment	
Repair kit	<b>Yes</b>
Compressor	<b>Yes</b>
Total cost ex VAT	<b>3781,68</b>
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>259,80</b>



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>283,80</b>
---	---------------





Luggage space cover, Missing, E - Replace 240,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 366,35



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 390,35



Door F L, Bump(s), PDR - Knock out without painting 63,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00





Registration Document, Missing, E - Replace 150,00

*No pictures to display*

Ignition key, Missing, E - Replace 150,00



Interior, Dirty, Cleaning 150,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper moulding R, Scratch(es), E - Replace 75,00



Wing R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Rearlight L, Scratch(es), Acceptable 0,00

*No pictures to display*

Tailgate, Scratch(es), Acceptable 0,00

*No pictures to display*

Headlight R, Scratch(es), E - Replace 396,00



Ignition key, Missing, E - Replace 150,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 452,20

