

AUDI A3: 1TUR426

Vinnumber:	WAUZZZ8V1FA125994	Versionname:	
First Registrationdate:	1/01/2021	Fiscalpower:	
Expertise Mileage:	69201	Power Kw:	
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2313
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

GPS storage		Central consol F
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Total cost ex VAT	2530,52
Window R L door, Scratch(es), E - Replace	99,00












Door frame R L, Damaged, E - Replace	62,00
--------------------------------------	-------



Registration Document, Missing, E - Replace	150,00
---------------------------------------------	--------

No pictures to display

Wing trim R L, Damaged, E - Replace	59,00
	
Luggage space cover, Missing, E - Replace	50,00
	
Front bumper, Bump(s), Le - Replace and paint	735,00
	
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
	
Sill trim R, Scratch(es), It - Spot repair	115,56
	
Interior, Dirty, Cleaning	72,00
	
	
Side window R L, Scratch(es), E - Replace	74,00
	
Covering interior front pillar L, Burned, Smart repair	110,64
	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Ceiling, Burned, Smart repair	64,32
-------------------------------	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)	235,80
---------------------------------------------------------	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Certificate Of Conformity, Missing, E - Replace	150,00
-------------------------------------------------	--------

No pictures to display