



BMW 4 GRAN COUPE: 1TVN808

Vinnumber:	WBA4B51010D419083	Versionname:	2.0 420D (120KW) GRAN COUPE
First Registrationdate:	2/01/2015	Fiscalpower:	
Expertise Mileage:	177432	Power Kw:	120
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2310
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	HD	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunction		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/45/18/95 V LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		1954,96
Alloy rim F L polished, Scratch(es), E - Replace		277,44





Interior, Dirty, Cleaning

100,00



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R R polished, Scratch(es), E - Replace

277,44



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)

302,16



Alloy rim R L polished, Scratch(es), E - Replace

277,44



Cigar lighter, Missing, E - Replace

21,60



Registration Document, Missing, E - Replace 150,00



Bodywork, Dirty, P - Check 0,00

No pictures to display

Bumper moulding F L, Broken, E - Replace 17,28



Alloy rim F R polished, Scratch(es), E - Replace 277,44

