


PEUGEOT 508: 1EOE312

| | | | |
|-------------------------|--------------------------|--------------|---------------------------|
| Vinnnumber: | VF38E9HL0CL083715 | Versionname: | 508 SW Style 115PK |
| First Registrationdate: | 5/02/2013 | Fiscalpower: | |
| Expertise Mileage: | 94171 | Power Kw: | 84 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2601 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Panoramic roof |
| GPS storage | HD | Central consol F |
| Windows electric F | | Luggage cover |
| Windows electric R | | Front parking sensors |
| Cruise Control | | Rear parking sensors |
| Steering wheel multifunctional | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|------------|---------------------|------------|
| Power steering | Yes | Battery functioning | Yes |
| Airco functioning | OK | Sound engine | OK |
| Tires wear profile | OK | Clutch test | OK |
| Idle position | OK | Wiper fluid level | OK |
| Engine startingtime | OK | Lighting | OK |
| Exhaust gass | OK | Wiperblades | OK |
| Transmission | OK | | |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 215/55/17/98 V LightMetal | | | |
| Winter tyres: | Fr.L. | Bridgestone: 6 mm | Fr.R. | Bridgestone: 6 mm |
| | Re.L. | Bridgestone: 6 mm | Re.R. | Bridgestone: 6 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 841,88 |
|-------------------|---------------|

| | |
|--|-------------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|--|--------------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|



| | |
|-------------------------------|-------------|
| Door R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display

| | |
|------------------------------------|---------------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|---------------|



| | |
|---|--------|
| Door R L, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |



| | |
|--|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Stone chip(s), Windscreen repair | 0,00 |



| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|--|-------|
| Door F L, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|-----------------------------------|------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |