



BMW 5: 1GIV542

Vinnumber:	WBA5N21030D495995	Versionname:	5 GRAN TURISMO 520dA
First Registrationdate:	19/02/2014	Fiscalpower:	163PK Aut.
Expertise Mileage:	103697	Power Kw:	120
Bodytype:		Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3706
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear







	245/50/18/100 H LightMetal			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		3219,70
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		369,84



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)		382,02
---	--	---------------

	302,02
Bumper R, Damaged, Le - Replace and paint	766,80
	
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	369,84
	
Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
	
Interior, Dirty, Cleaning	100,00
	
Roof, Bump(s), PDR - Knock out without painting	63,00
	
Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Ignition key, Missing, E - Replace	150,00
No pictures to display	
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02



Front bumper, Scratch(es), LI - Repair and paint (complete)

254,16

