



VOLKSWAGEN TIGUAN: EU8779

Vinnnumber:	WVGZZZ5NZDW109728	Versionname:	TIGUAN 4M Sport&Style
First Registrationdate:	28/05/2013	Fiscalpower:	136PK
Expertise Mileage:	193046	Power Kw:	100
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1504
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	SD	Sun Roof electric
GPS storage		Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Steering wheel multifunctional		Front parking sensors
Seats F heated		Rear parking sensors
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	235/50/18/101 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Compressor **Yes**

Total cost ex VAT 480,08

Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00










Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Tyre repair kit, Incomplete, F - Replace 0,00

<i>No pictures to display</i>		
Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)		290,08
		
Door R R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		