



TOYOTA AVENSIS: 1EPY506

Vinnumber:	SB1ED76L10E109501	Versionname:	
First Registrationdate:	19/02/2013	Fiscalpower:	
Expertise Mileage:	132447	Power Kw:	91
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4432
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Type of Tow bar	Tow bar fixed
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/17/98 V LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2217,18
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------


Alloy rim F L polished, Scratch(es), E - Replace 235,20



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), E - Replace 235,20



Interior, Dirty, Cleaning 75,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Rear window, Scratch(es), E - Replace 370,00

