



**PEUGEOT 5008: 1DPH054**

Vinnnumber:	<b>VF30E9HR8CS148590</b>	Versionname:	<b>5008 e-HDi Allure STT FAP BMP 112PK Aut.</b>
First Registrationdate:	<b>12/07/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>53691</b>	Power Kw:	<b>82</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2102</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Panoramic roof	
GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/55/16/95 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 3 mm</b>	Fr.R.	<b>Uniroyal: 3 mm</b>
	Re.L.	<b>Uniroyal: 3 mm</b>	Re.R.	<b>Uniroyal: 3 mm</b>

**Assistance equipment**

Total cost ex VAT	<b>580,60</b>
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>211,80</b>



**Front bumper, Scratch(es), LI - Repair and paint (complete)** **211,80**







Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Bump(s), PDR - Knock out without painting 0,00



Protection plate M, Tear, E - Replace 62,00



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), LI - Repair and paint (complete) 0,00

