


SKODA Octavia: 1GIQ651

Vinnnumber:	TMBAG7NE9D0018905	Versionname:	OCTAVIA BER Ambition
First Registrationdate:	18/02/2014	Fiscalpower:	105PK
Expertise Mileage:	138809	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2806
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1872,55
-------------------	----------------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Interior, Dirty, Cleaning	100,00
---------------------------	---------------





Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Luggage space cover, Unclassped, Repair/replace (lump sum) 20,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Bump(s), LI - Repair and paint (complete)

318,35

