



FORD C-MAX: 1PNB162

Vinnumber:	WFOJXXWPBJCK09002	Versionname:	C-MAX Trend St/St 95PK
First Registrationdate:	6/07/2012	Fiscalpower:	
Expertise Mileage:	194956	Power Kw:	70
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2415
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	3167,67
-------------------	----------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Roof pillar L, Bump(s), LI - Repair and paint (complete)	220,18
--	---------------



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56
---	---------------

(complete)



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Damaged, E - Replace 487,20



Front bumper, Bump(s) and scratch(es), Le - Replace and paint 735,00



Roof pillar R, Difference in color, It - Spot repair 115,56



Seat adjuster F L, Incomplete, E - Replace 12,00



Interior, Dirty, Cleaning 50,00



Rearview mirror L complete, Broken, E - Replace 168,00



Wing F R, Bump(s), LI - Repair and paint (complete) 220,18



Trunk lid covering R, Damaged, Smart repair 110,64

