



FORD Transit Connect SWB: UZ8521

Vinnnumber:	WF0TXXTPTCT31906	Versionname:	TRANS.CONNECT SWB T220 Trend FAP(E5)90PK
First Registrationdate:	12/02/2013	Fiscalpower:	
Expertise Mileage:	180982	Power Kw:	66
Bodytype:	Transporter	Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2326
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	Tow bar fixed
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	195/65/15/95 T Steel			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1246,82
Wheel cover R R, Missing, E - Replace	22,50



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	-------------

No pictures to display

Interior, Dirty, Cleaning	100,00
---------------------------	---------------




Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Wing R L, Bump(s), L L, Repair and paint (complete)	234,45
---	---------------

Wing R L, Bump(s), LI - Repair and paint (complete) 231,15



Sliding door R, Bump(s), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), LI - Repair and paint (complete) 362,02



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Seat cover F R, Burned, E - Replace 300,00



Wing R R, Bump(s), LI - Repair and paint (complete) 231,15

