



VOLKSWAGEN Sharan: 1ERW858			
Vinnnumber:	WVWZZZ7NZDV025753	Versionname:	SHARAN Highline BMT DSG 136PK Aut.
First Registrationdate:	5/03/2013	Fiscalpower:	
Expertise Mileage:	85828	Power Kw:	100
Bodytype:	MPV	Body color	Silver
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2328
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	225/50/17/98 H LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	No	Compressor	No
Total cost ex VAT			1143,51
Wing R L, Scratch(es), Acceptable			0,00

No pictures to display	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	302,16





Compressor, Missing, E - Replace 0,00



Rearview mirror housing R, Broken, E - Replace 72,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bump(s), PDR - Knock out without painting 159,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight R tailgate, Scratch(es), 67 - Polish 55,19



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Door R R, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 302,16





Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

