



**OPEL VIVARO: 1UBY919**

Vinnumber:	<b>W0L2F711FFV614560</b>	Versionname:	
First Registrationdate:	<b>30/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>167944</b>	Power Kw:	<b>88</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV16</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F		Central consol F	
Radio multimedia		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/65/16/107 T Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 8 mm</b>	Re.R.	<b>Continental: 8 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>
-------------	-----------

Total cost ex VAT	2443,11
-------------------	---------

Rearview mirror housing L, Scratch(es), Smart repair	110,64
--	--------



Interior, Dirty, Cleaning	150,00
---------------------------	--------





Rearlight L, Damaged, E - Replace 91,50




Wheel cover F R, Missing, E - Replace 22,50



Radio, Incomplete, Forfeit 50,00



Front bumper, Scratch(es), Smart repair 110,64



Backrest cover R M, Damaged, E - Replace 300,00



Ignition key, Missing, E - Replace 150,00

*No pictures to display*

Wheel cover F L, Scratch(es), E - Replace 22,50



Spare wheel, Missing, E - Replace 153,60



Internal Boot Lining R, Bump(s), Smart repair 110,64




Wheel cover R L, Missing, E - Replace 22,50



Internal Boot Lining L, Bump(s), Smart repair 110,64



Door R L, Scratch(es), LI - Repair and paint (complete) 238,76



Rearview mirror housing R, Damaged, LI - Repair and paint (complete) 115,56



Roof, Bump(s), LI - Repair and paint (complete) 361,13



Wheel cover R R, Damaged, E - Replace 22,50



Seat cover F L, Damaged, E - Replace 300,00

