



RENAULT Kangoo Express: 1ESV118

Vinnnumber:	VF1FW15H548587433	Versionname:	KANGOO EXPR.B/F MAXI Confort FAP 90PK
First Registrationdate:	12/03/2013	Fiscalpower:	
Expertise Mileage:	185144	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	No		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	NOT OK		
Registration Certificate Car (BE):	No		

Options

Windows electric F		Central consol F	
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	No
Tires wear profile	OK	Power steering	No
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 T Steel			
Winter tyres:	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 5 mm
	Re.L.	BF Goodrich: 5 mm	Re.R.	BF Goodrich: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1878,04
-------------------	---------

Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Centre console, Tear, Smart repair	110,64
------------------------------------	--------



Interior, Damaged, Forfeit	300,00
----------------------------	--------





Bodywork, Glue residues, Acceptable 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Registration Document, Missing, E - Replace 150,00



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 361,13



Rearview mirror R complete, Damaged, E - Replace 138,00





Ignition key, Missing, E - Replace 150,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner F L, Scratch(es), LI - Repair and paint (complete)	115,56
	
Door F R, Bump(s), PDR - Knock out without painting	82,80
	
Door R R, Bump(s), LI - Repair and paint (complete)	238,76
