



VOLKSWAGEN Golf: 1GA0938

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber: | WVWZZZAUZEP051672 | Versionname: | GOLF BER Trendline 105PK |
| First Registrationdate: | 9/12/2013 | Fiscalpower: | |
| Expertise Mileage: | 137530 | Power Kw: | 77 |
| Bodytype: | Hatchback | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2827 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|------------------------------|------------------------------|
| Windows electric F | Central consol F |
| Cruise Control | Luggage cover |
| Steering wheel multifunction | Front parking sensors |
| Radio multimedia | Rear parking sensors |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |
| Adaptive cruise control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
| | 165/65/15/91 T Steel | | | |
| Winter tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1389,20 |
|-------------------|----------------|

| | |
|---------------------------------------|---------------|
| Rear window, Scratch(es), E - Replace | 370,00 |
|---------------------------------------|---------------|



| | |
|---|---------------|
| Bumper R, Crack, Le - Replace and paint | 651,00 |
|---|---------------|



| | |
|---|---------------|
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 308,20 |
|---|---------------|



Wheel cover F R, Scratch(es), E - Replace 30,00



Mirror side blinker L, Damaged, E - Replace 30,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display