



**FORD Focus: 1DPH057**

Vinnumber:	<b>WF0LXXGCBLC02965</b>	Versionname:	<b>FOCUS CLIP. ECONetic T.Trend 95PK</b>
First Registrationdate:	<b>12/07/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>140206</b>	Power Kw:	<b>70</b>
Bodytype:	<b>Break</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4814</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Fulda: 5 mm</b>	Re.R.	<b>Fulda: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>No</b>
------------	------------	------------	-----------

<b>Total cost ex VAT</b>	<b>1784,97</b>
--------------------------	----------------





















<b>Windscreen, Stone chip(s), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>
--	---------------



<b>Ceiling, Burned, E - Replace</b>	<b>494,00</b>
-------------------------------------	---------------

		Tyre repair kit, Missing, E - Replace	210,53
		Tailgate, Bad repair, Paint	0,00
		Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>			
		Cigar lighter, Strained , E - Replace	18,00
		Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
			
		Wheel cover R L, Scratch(es), E - Replace	30,00
			
		Door panel F L, Scratch(es), Acceptable	0,00
		Wheel cover F R, Scratch(es), E - Replace	30,00
		Bumper corner R R, Scratch(es), It - Spot repair	115,56
		Seat cover F L, Burned, E - Replace	360,00



Bodywork, Not original part, Acceptable	0,00
---	------

*No pictures to display*

Tailgate, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Seat cover R L, Stain, Cleaning	25,00
---------------------------------	-------



Steering wheel, Worn, Acceptable	0,00
----------------------------------	------



Model badge R, Worn, Acceptable	0,00
---------------------------------	------

