



PEUGEOT Boxer 335: 1EFJ144

Vinnnumber:	VF3YCTMFC12310502	Versionname:	BOXER 335 B/F LWB L3H2 FAP 130PK
First Registrationdate:	15/11/2012	Fiscalpower:	
Expertise Mileage:	85654	Power Kw:	96
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV21
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/70/15/109 S Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 8 mm	Re.R.	Bridgestone: 8 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2901,58
Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	232,88



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	327,15
---	--------



Wheel cover F R, Damaged, Acceptable 0,00



Rear bulkhead lining, Bump(s), Smart repair 110,64




Rearview mirror housing L, Scratch(es), Smart repair 110,64



Door moulding Lower R R, Damaged, E - Replace 91,50



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Spare wheel compartment lining R L, Bump(s), Smart repair 110,64



Door trim R L, Scratch(es), E - Replace 91,50

Door trim R L, Scratch(es), E - Replace 81,00



Front bumper, Scratch(es), Smart repair 110,64



Ignition key, Missing, E - Replace 150,00

No pictures to display

Spare wheel compartment lining R R, Bump(s), Smart repair 110,64



Internal Boot Lining L, Damaged, Smart repair 110,64



Internal Boot Lining R, Damaged, Smart repair 50,00



Bumper R, Damaged, E - Replace 329,40



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 327,15



Internal Boot Lining R, Damaged, Smart repair	110,64
---	--------



Internal Boot Lining L, Damaged, Smart repair	50,00
---	-------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display