



PEUGEOT 208: TX7668

Vinnnumber:	VF3CC8HR0DT029267	Versionname:	208 BER Active 68PK
First Registrationdate:	1/03/2016	Fiscalpower:	
Expertise Mileage:	122767	Power Kw:	50
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	-1100KM	Parking lot:	4513
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1284,27
Rearview mirror housing R, Stain, 67 - Polish	55,19



Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------



Seat cover F L, Stain, Cleaning	25,00
---------------------------------	--------------




Wheel cover F R, Scratch(es), E - Replace 24,00



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Damaged, E - Replace 24,00



Door F L, Bump(s), PDR - Knock out without painting 63,00



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 248,40



Wheel cover F L, Scratch(es), E - Replace 24,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 246,56





Front bumper, Damaged, LI - Repair and paint (complete) 169,44

