



PEUGEOT 508: 1EMW213

Vinnumber:	VF38URHC8CL076971	Versionname:	508 SW RXH BMP STT 163PK Aut.
First Registrationdate:	25/01/2013	Fiscalpower:	
Expertise Mileage:	183923	Power Kw:	120
Bodytype:	Break	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Diesel	Oil level:	OK
Maintenance:	BINNEN 8000KM	Parking lot:	4108
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining	Lining leather		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Runflat	Yes

Total cost ex VAT	1537,02
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Dashboard, Deformed, Acceptable	0,00




Door F R, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (partial) 0,00



Moulding windscreen L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Worn, Acceptable 0,00



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Bad repair, Paint 0,00



Wing trim R R, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display